

28 Oct 1970 Stock Investors Volunteered & They
Organized Wasatch Mountain Railway and
Development Company Tonite at Wasatch Co Bldg.
Lowe Ashton President
R. Raymond Green Vice Pres.
Charles H. Nielson 2nd Vice Pres.

Board of Directors Chosen:

Dr. Stephen Carr

Edward McLaughlin Sec

Dennis A. Spindlelove

Thomas I. Baum

Leon Ritchie

Jay Red Edwards

31st Oct. 1970 2nd Board of directors Meeting
Hub Cafe 7: A.M.

work detail on 2 dips above dam & rails
pulled out & 11 ties pulled out, 4 ties
laid & one rail cut to fit & laid.

November 1970 Sunday

Monday

Tuesday

1

To be Done
in Nov '70

✓ Basic Track
Repair &
Mtce.

✓ ⁶¹⁸ Engine Work
To Prepare
To Move

✓ Move #618
Engine onto
Western & Garfield
siding 11-1, 11-15,
11-28,

✓ Assemble
all cars
Engine &
caboose

Move 1st
Train up
Provo Canyon

Frank O'Brien
Materials into
Heber

✓ 50000 Tools
& Labor

2

3

Tried to Get
Dean Bates
Full Time
Ans - No Mr.
Harry McMillan

8

9

10

Total expenditure Got Glen Allison
this week Started on Roller
4 men 3 days Coaster track.
2 men 3 days
Dynamite

Roller coaster fine
Re-Tamped Deep dip
above dam,
gravel car broke down
Need 50¢/ton Road
Base

15 Sunday
#618 Engine
Moved 1 city
block on
Fairgrounds

Pulled out 9 Ties
at 16 Deer Creek Dam
9 Ties into Charleston
(Fishplant) area
Dynamite Rock work
Final measure Ties

17 Need Gravel
Hauling device
6 Ties in at
Charleston Fishplant
Rock hand work
above Dam
& Dynamite

22

23

24

Ties

Ties

29

30

Wednesday

Thursday

Friday

Saturday

4

5

6

7

~~Pheasant~~
~~Hunt~~
~~in St. Geo.~~

5 Pledges to Pres Call
 11 RR Meetin
 Lowe's Office
 Work on #1
 Shallow dip above
 Dam. Ordered Ties
 Obtained ^{old Army} County Dump
 Truck - got it
 Running - Ed. Mc L.
 & Dennis & Jim Berry

12

Rain - Snow
 Fine' shallow Dip
 Work on Rock
 11 ties in
 at 2nd
 Dip above
 dam.

13

Dynamite
 Get Rock off Tracks
 above Dam.
 Letter to Lowe Ashton
 8 more ties in
 in 2nd dip above
 dam.

14

More dynamite
 Need Ballast
 #618 begins to mo
 We sent 400 Ties to
 Jimmy Barnes
 Work on Water Cros
 Cement culvert to
 Water Crest.
 Rig Boom.

18

Trestle ties cut.
 Switch ties cut.
 3 more ties in
 4 Ties down
 To Trestle

19

Rig Pipe Boom on
 Dinky Engine
 Cold snow
 4 Trestle ties in

20

4 More Trestle ties
 Replaced.
 Dinky Engine Voltage
 Regulator went out

21

Directors
 Meeting
 Last Track
 Crew work

25

Ties

26

Thanksgiving

27

28

No directors
 Meeting except
 on Carr Dike.

December 1970 Sunday Monday Tuesday

↓
Musts:

1

Clean up
Depot yard

Clean up Depot
inside

Paint 4 Cars

6

7

8

✓ Repair Caboose

Paint at
Turn Tires on SL Malley

6/8 Arrived
in Heber.

+ car out of
Pocatello

13

14

15

✓ 4 cars out of
ogden

Chain on
Track

35 loaded in
calif.

✓ ~~2.54~~ Train into
Heber 7 Dec 70

20

21

22

Frank O'Brien
Material into
Heber

✓ #6/8.4
4 cars +
1 caboose
into Heber

27

28

29

Wednesday	Thursday	Friday	Saturday
2	3	4	5
9 <i>Chamie on Track</i>	10	11	12 <i>Director Meet. Safety Inspector Mr Shepherd Mr Ozmond Jim Mr Ray Lloyd.</i>
16	17	18 <i>HP Gave us Xmas Present 2 P.M. Tourist Old Vintage Passenger car</i>	19 <i>Park Council</i>
23	24	25	26
30	31		

January

Sunday

Monday

Tuesday

Engine 618
Rerail 2 x
in Jan 71

Clear Titles

Legislative Action

Governors Day
1184 People Rides

3

4

5

State Ho

1 car from
Pocatello

~~1184~~
People
Rode Train
Free

Turn Tires on SL
#110

10

11

12

#35 loaded in
California

1-5 PM
1184
People
Rode
Train

Lowe E
Blain Kaye
Tribune
Man

17

18

19-72

⁶⁷
24/31-60

25-66

26-65

Wednesday Thursday Friday Saturday

1

2 ⁶¹⁸
Engine
Fired Up
Clear line

Week

6

7

8

9 2:30 AM Snow Plowed
~~11:45~~
200 People
Ride down
Canyon. Engine
De Rail @ Rieskes
Governor There

13

14

15

16 1 PM - Bd of
Directors @ Lowe
Over 60,000 Pledge
Spent \$600 Bills \$500

20-71

21-70

22-69

23-68

27-64

28-63

29-62

30-61

February

Sunday

Monday

Tuesday

1971

1-59

2-58

7-53

8-52

9-51

Clean Grounds

Clean Depot

Frank O'Brien
Pieces Assembled

Legislative

14-46

15-45

16-44

21-39

22-38

23-37

28-32

Wednesday	Thursday	Friday	Saturday
3-57	4-56	5-55	6-54
10-50	11-49	12-48	13-47
a week in Feb -			
17-43	18-42 Lobby session	19-41	20-40
24-36	25-35 Lobby session	26-34	27-33

March	Sunday	Monday	Tuesday
		1-31 Hoped Resolution to be Read.	2-30 7d RR Title Clear on Site of way Leon Frazier-No
Finish turn tires on #110 Heroic Assembly of All equipment	7-25	8-24	9-23
One more train up canyon or 2	14-18 Red Visited me Steve Belmont	15-17 Dennis Back Ed Lovelace gave us till 15 Apr 1971 to cross Muns.	16-16 can't unload #35 at Pross Brick & tile spur
	21-11	22-10	23-9
	28-4	29-3	30-2

Wednesday

Thursday

Friday

Saturday

3-29

H. Senate Bill 16
Passed
3rd Reading
of Legislature
Met Meet +
Lobby

4-28

5-27

6-26

10-22

11-21

#35 loaded
in Calif.

12-20

#110 tires
Finished

13-19

Directors
Meet.

17-15

18-14

Started
Digging
Pit @
Olmstead

19-13

Talked With
Mrs Walker
Re Crane
Rails into Pit
#35 @ Mouth
of Canyon

20-12

24-8

25-7

26-6

27-5

31-1

All Rolling Stock
Now into Heber
Valley

April

Sunday

Monday

Tuesday

Regroton[®]

chlorthalidone 50 mg.
reserpine 0.25 mg.

A long-acting
antihypertensive
combination
to help take the
pressure off...
smoothly

4

5

6

11

12

13

18

19

20

Geigy

25

26

27